

CITY OF CAPE TOWN  
ELECTRICITY GENERATION & DISTRIBUTION  
**ACCIDENT/DAMAGE REPORT**

INDICATE AREA WITH "X":

EAST		NORTH	x	SOUTH	
------	--	-------	---	-------	--

DEPOT:

Mowbray
---------

LOCATION OF INCIDENT : Lower Scott road  
DATE AND TIME OF INCIDENT : 21-02-2020  
DETAILS OF INCIDENT/DAMAGE : Contractor using JCB digger damaged cable

**RESPONSIBLE PARTY**

NAME :   
ADDRESS :

**IF COMPANY**

NAME :   
COMPANY REGISTRATION NO :  
ADDRESS :

**IF MOTOR VEHICLE ACCIDENT**

NAME OF DRIVER :  
ADDRESS :  
TYPE OF VEHICLE :  
REGISTRATION NO :  
REPORTED BY :  
ADDRESS :  
DATE AND TIME REPORTED :  
REPORT RECEIVED BY :  
CAUSE OF ACCIDENT :  
DATE REPORTED TO SAPS :  
POLICE STATION & CASE NO :

**WITNESSES**

NAME :  
ADDRESS :  
CONTACT NO :

**COST OF REPAIRS**

WORK ORDER NO :   
FINAL COST : R42 019.15

**OFFICIAL RESPONSIBLE FOR REPAIRS**

NAME : D Sullivan  
CONTACT UMBER : 0827786253

**NOTE:**

In the event of cable damage, please provide copies of all relevant documentation such as Way-leaves & Photographs and indicate if no Way-leave was issued or applied for.

In order to expedite this process, please e-mail this report to: [chantel.basson@capetown.gov.za](mailto:chantel.basson@capetown.gov.za)